

Le Phoque

Please return inclosed photos.

Owner maintain that vessel  
is twisted about the line of sheeting  
on the axis. Vessel was struck  
S. side aft. and plating on P. side  
is marked as you will see by the  
photographs. From about E.R. bulkhead  
aft.

The extent of the repairs that  
the Owner considers should be done  
will mean a C.T.L.

GAL



© 2019

Lloyd's Register  
Foundation

W479-0035