

128 FEB 1939

11

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME PARKHILLRpt. Nwe No. 97157**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


Nature of Survey Condition

The Newcastle Surveyors report this vessel placed in dry dock, bottom cleaned and coated, repairs to shell & deck plate stern gear & hatchways and minor repairs effected.

It is submitted the vessel appears worthy to remain as classed with record of survey 2.39 as recommended.

100A-1.
2.39 Bly.

See letter 6.3.39.
The Surveyors should be informed this vessel was originally supplied with 3 B. & 1 S. anchors ^(atten H) it is concluded that they are in error in reporting only 2 B. anchors ~~as being~~ on board.



© 2020

Lloyd's Register
Foundation

W48/014)