

the Surveyor examine the drain pugs of the Main Boilers?

the Surveyor examine all the mountings of the Main Boilers?

and of the Donkey Boilers?

39.

4 E

d by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

EL'S NAME

Kirnewood

Rpt.

Lat.

No. 109662

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

e of Survey

REPAIRS TO ENGINES ~~AND BOILERS~~ DUE TO DAMAGE THROUGH

Bombing.

Main injection valve chest-(cracked) & box on  
stump's side (cracked) both renewed.

Main end of ballast pump (broken) renewed.

Keels of 5 tunnel bearings (broken) replaced  
by steel plates.

It is submitted that  
this vessel is eligible to  
remain as CLASSED.

S.S. hr. 3 p.m. 7.40  
MBS per 4.40  
DBS due 11.30

© 2021

Lloyd's Register  
Foundation

1010-0101

far as seen is in a safe working condition & eligible in my opinion  
that such record