

Surveyors

Received from Chief Surveyors

NAME

"SINALOA"

Report

L. An

No. 2031.

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

Grounding

When due

(Examination while afloat)

Subj.: Indented deck plating & bulwarks to be dealt with
at the Owners' Convenience

The vessel requires to be specially examined at next
dry docking after Grounding on 4/4/36.

Vessel now examined while still afloat (Subsequent
fast on rocks - bottom badly set up
Grounding)

Information is awaited as to whether
the vessel is to be constructed as a

Lloyd's Register
Foundation
5.2.37.

3521-0191