

S.S. "MARZOCCO"

	P	S
No. 1, 2 plate from fwd. 4th. strake below sheer strake:	12 mm.	10 mm.
No. 3 plate from aft 4th. strake below sheer strake:	10 mm.	11 mm.
No. 2 plate from aft 5th. strake below sheer strake:	10 mm.	10 mm.

Reps. W₂T₁ - The fwd. stringer plate of pump deck p.d.p. also stringer plate in way of mooring bits damaged.

P₂ S₂ side bunkers, horizontal girder plate and brackets to stiffeners also hatch post angle removed.

Rivet turned pivots in top angles of hatch stiffening beams removed as found necessary.

Gears of skylight petio factory repaired.

One pipe of No. 4 d.b. tank in port side partly removed.

Three floors (from fwd.) in fore peak tank partly damaged.

To complete the survey: P.O. tank under engine & boilers to be examined internally & tested. Tank top & bilges in engine & boiler spaces to be examined. In addition cargo bottoms and wood sheathing on tunnel require to be removed as necessary and indicators to manoeuvring wheel of r.t. doors to be fitted.

It is stated that this will be done as soon as possible.

M.S.

f.c.d.



© 2021

Lloyd's Register
Foundation