

the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

and of the Donkey Boilers?

10.30.

to Chief Surveyors

Received from Chief Surveyors

SEL'S NAME

"MANSERPOOL"

Report

Liv.

No.

114350

For the ~~CHIEF SHIP SURVEYOR~~ and ~~CHIEF ENGINEER SURVEYOR~~.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

Duration of Survey

Special Survey No.1

When due

2.40


Noted.

YRM

25.6.40

*It is submitted that
this vessel is eligible for
THE RECORD. + Recd. 10.39*

Subject to the LP cylinder bottom being examined before the end of 6.42 and to a number of condenser tubes being renewed at the first opportunity.



© 2021

Lloyd's Register Foundation

USS-00 96

The machinery of this vessel, in my opinion, is in a condition eligible in my opinion to remain as classed, with...