

content of Examination and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars

55 L2. N° 3-
55 Mch N° 1



Lloyd's Register of Shipping.

71, Fenchurch Street,
Wokingham, Berks.

London, 19th October, 1939.
E.C.3.

H.

Secretary
To the Surveyor at LIVERPOOL.

Vessel's Name, s.s. "MARDINIAN"

QUESTION.

ANSWER.

I shall be glad if you will ascertain and let me know what arrangements the Owners propose making for the Boiler Survey, which became due at the end of August last, to be carried out.

Date:— 25th October, 1939.

In reply to enquiry the Owners write as follows:-

"We have pleasure to acknowledge and thank you for your letter of October 21st.

The vessel is expected shortly in the United Kingdom when we will endeavour to deal with the completion of the Annual Boiler Survey."



© 2021

Lloyd's Register
Foundation

W55-0150

board (if Ship and whom?)

Class

Items:--

- Copper, (Ste)
- When fit
- Boats
- Masts,
- Condition (Sta)
- Equipm
- Anchors
- Cables
- " "
- " "
- Chain
- Hawser
- Standin
- Sails

el in the remain a

slig