

206

206




© 2020

Lloyd's Register
Foundation

Showing corrugated
part cut out

There was a half bolted
and half riveted patch on
each side of them, also
welding

152
RETAIN



© 2020

WS75-0049

Lloyd's Register
Foundation