

CABLEGRAM received from the Surveyors at SINGAPORE

Date of receipt: 10. 4. 30.

TRANSLATION.

HUNTRESS

IDTYP - Deep tank(s)
IBDYN - Frame(s)
LAHTE - At
HYTVU - Deck(s)
KYMVE - About
OKKCI - 6 feet
LYHBY - Missing
HYDOP - Deck beam(s)
KYMVE - About
OHTFE - 2/20"
ICFAN - Shell plating
LIWAF - Found
LEOLM - Cracked
MISOKM - Through
ICUFU - Rivet hole(s)
KYUSC - And
LUTEN - Leaking
MEBYP - Recommended
NUTUD - Cargo
MISXO - To be
DISCHARGED
GUKLI - Vessel is to be drydocked
MISBY - Thoroughly
LIHGI - Examined
KYUSC - And
KHIUF - Repairs must be carried out before vessel proceeds to sea
KIPET - Temporary repairs cannot be efficiently carried out afloat
MAACK - Owners' agents cable (have cabled)
LYZYF - Owners agree.

*Please ask in
Eng. Classing Letter*



© 2021

Lloyd's Register
Foundation

W 582 014