

Surveyors

5. 7. 30.

Received from Chief Surveyors

NAME

See Mr. Huntress' Report

No. 4709

For the CHIEF SHIP SURVEYOR ~~and~~ CHIEF ENGINEER SURVEYOR.


(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

Survey

When due

It is submitted the Durban Surveyor be informed that after repairs had been effected to the deep tank, the tank was filled and tested and the new work found satisfactory but several bad leaks were noted particularly in the after bulkhead in way of the starboard stringer.

Several rivets were renewed and a small bolted patch fitted, but the Surveyors state that the bulkhead requires a thorough examination and a further test of the deep tank and recommend that the after bulkhead of the deep tank be repaired.



Wama.
5.7.30.



© 2021

Lloyd's Register
Foundation

W582 0302