

NO RESPONSIBILITY WILL BE ACKNOWLEDGED FOR ANY CONSEQUENCES ARISING OUT OF STRIKES, COMBINATIONS OR OTHER LABOUR DISTURBANCES.
OFFERS FOR DRY DOCKING ARE SUBJECT TO DOCK BEING AT LIBERTY. ALL TRANSPORTING AT OWNERS' RISK.

R & H. GREEN AND SILLEY WEIR, LIMITED.

SHIP AND ENGINE REPAIRERS,
BOILER MAKERS, ELECTRICAL ENGINEERS, IRON & BRASS FOUNDERS.

TELEPHONE NUMBERS:
GENERAL OFFICES: ALBERT DOCK 2121 (5 LINES)

Works:

BLACKWALL YARD: EAST 4171 & 4172.
ROYAL ALBERT DOCK: ALBERT DOCK 1641 (3 LINES)
CENTRAL WORKS, ROYAL ALBERT DOCK: ALBERT DOCK 1506.
SURREY DOCKS: NEW CROSS 3187 & 3188.
MILLWALL DOCK: EAST 4611 & 4612.
TILBURY WORKS: TILBURY 53 & 113.

CITY OFFICE: CORY BUILDINGS, FENCHURCH STREET, E.C.3.
TELEPHONE: AVENUE 6357 (3 LINES). TELEGRAMS: INTERKNIT, FEN, LONDON.

PLEASE ADDRESS YOUR REPLY TO THE FIRM AND QUOTE

OUR REF. GM/IS
YOUR REF.

TELEGRAMS: "REPAIRS, ALDOCK, LONDON."

General Offices:

Royal Albert Dock,
London, E.16.

STATIONS:—SILVERTOWN OR CONNAUGHT ROAD, L. & N.E.R.



12th September 1928

The Secretary,
Lloyd's Register of Shipping,
71, Fenchurch Street. E.C. 3.

Dear Sir,

S.S. "NARDANA".

We have been instructed to instal the Bauer-Wach System in the above named vessel, and we therefore beg to submit herewith, print No. 11035, in duplicate, showing the proposed stiffening to the Tank Top in way of the turbine and gearing, for your consideration.

We remain,

Yours faithfully,

For R. & H. Green and Silley Weir Ltd.

Director.

ENCLOSURE

Lloyd's Register
Foundation

W61-0566

Referred to the Chief Ship Surveyor.

*Submitted for approval as amended
13 SEP 1928
10/13/28
RM*

"NARDANA"

Itr. 12/9 Ansd. 14/9

Stiffening to tank top
inway turbine and gearing
for Bawer-Wach installation

1 plan 1 retained

p.c. London.



© 2019

Lloyd's Register
Foundation