

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 5 Mar 1931

When handed in at Local Office 5 Mar 1931

Port of NEWCASTLE-ON-TYNE

No. in Reg. Book.

Survey held at South Shields

Date, First Survey 27 Feb

Last Survey 27 MARCH 1931

70812 on the Wood, Iron or Steel *See* "FERNMOOR"

TONNAGE:-

GROSS 5812

UNDER DK. 5578

NET 3666

Built at Newcastle

Owners

Moon Line Ltd

Managers

W. Runciman & Co Ltd

By whom

Owners' Address

Port belonging to

When 1922

MONTH.

9

Surveyed Afloat or in Dry Dock? Dry Dock

Name of Dock Brigham Cowan Dock

Destined Voyage

WB=CellDBorDBa

feet; uE&B

feet; f

total capacity

tons. FPT

tons; APT

tons; MT

feet

feet

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 4185

Port Hull

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

Society's Freeboard (if assigned) as painted on Ship and now verified

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Docking after stated grounding near Belfast

hook (voyage Manchester to R. Tyne) on 31/1/31.

Now done :- Vessel placed in dry dock. Bottom and rudder cleaned examined and recoated.

No damage due to stated grounding observed. Minor repairs effected.

SUMMARY OF DAMAGE REPAIRS:-

Renewed

Removed and Faired or Repaired

Faired or Repaired in place

Shell Plates.

Frames.

R. Frames.

Floors.

Beams.

Str. Plates.

Dk. Plates.

Other Items:-

PRESENT CONDITION OF THE

Decks

Caulking of Decks

Coamings

Beams & Fastenings

Outside Plating

Breasthooks

Transoms

Frames

Reverse Frames

Longitudinals

Transverses

Floors

Keelsons

Stringers

Inner Bottom Plating

State if Tanks have been examined inside

State if Tanks now tested

Bulkheads

Ceiling

Cement or Asphalt

(State which.)

Rudder

Steering gear and its connections

Windlass

Have Pumps now been examined and found efficient?

Have Sluice Valves now been examined and found efficient?

Have Watertight Doors now been examined and found efficient?

Have Ventilators and their Coamings been examined

and found efficient?

Dblig. Plates under Sounding Pipes

Engine Room Skylights

Coal Bunkers, Open'gs, Lids, &c.

Scuppers

Cargo Hatchways

Hatches

Planking of Wood Vessels

Caulking

Treemails

Breasthooks & Stems

Transoms, Pointers, & Gatches ditto

Timbers of Frame at openings ditto

Ditto ditto at other places ditto

Stringers, Clamps & Shells ditto

Salting

(State if examined.)

Copper, or P.M. of Wood Vessels

(State if on Field)

When put on, Month

Boats

Masts, Yards, &c.

Condition, how ascertained

(State if wedges removed)

Sails

Equipment letter

Anchors, No. of

Cables (State if now ranged)

" length

(on board)

" Rule length

Hawser & Warps

Standing and Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

This vessel is eligible, in my opinion, to remain as classed and to have record of survey 3.31.

Survey Fee (per Section 20) £

Special Damage or Repair Fee (if any) (per Sec. 20) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for,

19

Received by me,


19

Committee's Minute/

Character Assigned

100 A1
Shelter deck with freeboard
S. 3-31

Surveyor to Lloyd's Register of Shipping.



© 2020

Lloyd's Register Foundation

W612-0144