

Double Bottoms at ...
 " at intermdt. Bkts. 9.5 9.5
 " Angles or Bulb Angles
 SIDE KEELSONS, Number

Ship Surveyor _____ Received from Chief Ship Surveyor _____

ME Steel 22 "CANADIAN NAVIGATOR" Rpt. MH. No. 1762

of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points entered in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Entry

*no return 2 1/2 w
 of 3 1/2 w*

Before this case receives the consideration of the Committee, the Surveyors be requested to state whether the 2nd Deck has been constructed in accordance with approved plan ✓ of no, to forward copy of this plan.

*M. A. S.
 25-12-19*

12/19



© 2021

Lloyd's Register
 Foundation
 W 661-0072

1x.56-3/4
 1x.46-
 5x.50-3.5x
 .46-
 .46
 .36
 5x3.5x
 5x.5
 x.32
 x.32
 .32
 3
 .48
 5x5x.48
 .40-.30

Angle on ditto.....						
Tie Plates.....						
Deck. Material and thickness <i>Steel</i>						