

## REPORT of SURVEY for REPAIRS, &amp;c.

Writing Report 11 Nov 27 When handed in at Local Office 11 Nov 27 Port of Newcastle-on-Tyne

Survey held at South Shields Date, First Survey and Last Survey 8 Nov 1927

1701 on the Wood, Iron or Steel S.S. "UPMINSTER"

TONNAGE: Built at Sunderland By whom Isbourne, Graham &amp; Co Ltd When 1917 3

DER DK. 1733 Owners Hudson S.S. Co Ltd Owners' Address (if not already recorded in Appendix to Register Book)

1272 Managers Port belonging to London

veyed Afloat or in Dry Dock? Dry DK Name of Dock T.D.E. Dry DK. Destined Voyage

= Cell DBor DBa feet; uE&amp;B feet; f feet } Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements).

ul capacity tons. FPT tons; APT tons; MT feet tons. }

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

st Report, No. 80716 Port NWC

Medical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent repairs. Repairs due to other causes; account of Damage (the cause of which must be stated) should be summarised in the form shown below. Whenever the placement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on back of this form. State also the dates and initials of any letters respecting this case.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

PAIRS, OR EXAMINATION AS PER RULE, FOR Docking.

Done — Vessel placed in dry dock, Bottom &amp; Rudder cleaned examined and

oated. Rudder lifted

ar and Tear Repairs. Three rudder pintles &amp; one locking pintle renewed. One pintle

h renewed. Several odd shell rivets renewed where worn. Several slack

ge keel rivets renewed on both sides of vessel. Freeboard checked.