

summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the date and (with)

to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

ROWAN BANK

Report

GLS

No. 63023

**For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)


(2<sup>ND</sup> No. 2 SURVEY PARTLY HELD.) GENERAL EXAMINATION.

When due 9-39 WITH YEAR OF GRACE GRANTED When proposed to be completed EXAMINED 10-40-6 MONTHS POST

Portion of Survey held, &c. N° 5 hold, tween dks & D.B. tank, masts, rigging, steering-gear & windlass examined also N° 5 D.B. tanks tested.

Permanent repairs are required to the E.R. tank top plating forward (P.S.) also some floors & reverse frames in tanks, to E.R. bulkhead, tween deck bunker beam brackets and fire deck plating at the S.S.

Subject to indented plating on the port side of N° 1 hold being dealt with.



© 2020

Lloyd's Register  
S.S. PART HELD RPS

W71-0288

Particulars

cient?

not expand

Treenails

Cables (State if now rang