

Gates at Chiswick ... has been made good as in evidence of same could be seen

SUMMARY OF DAMAGE REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed								

W710-0241

2,500,11,21.

Sent to Chief Surveyors \_\_\_\_\_ Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME Steel S.S. "Orteric" Report N.Y.K No. 21925

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey Condition & Repairs. When due \_\_\_\_\_

Subject.

Indented plate port side N°4 strake between Nos 1 & 2 D.B. tanks to be dealt with at owners convenience.



© 2020  
 6.9.22

Lloyd's Register  
 Foundation

(per Sec. 20)  
 Travelling Expenses (if chargeable) £ : :  
 Second Surveyor's Fee (if any) £ : :

Received by me, [Signature]  
 19 \_\_\_\_\_  
William G. Little  
 Surveyor to Lloyd's Register of Shipping.

els.  
 Year  
 size  
 size  
 good.  
 sequent upon  
 ve record of  
 2.  
 8