

and 3rd and 4th  
Total under U  
Do. of Poop  
D. P. O. D. L.

5c, 12, 16.

F.E.

Received by Chief Ship Surveyor 29.6.18

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME Sheels War Balloon Rpt. Misc No. 71075

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 62.95 Depth "d" 18.16

Framing: Table No. 3 page 11 Description Bulb Angle as approved

Longitudinal No. 17915

Proportions Length = 13.42  
Depth =

Upper Deck Sheerstrake as approved.  
The downcom pump has not been fitted as approved in  
Standard Vessels.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  $\star$  100A-1 (Steel) as recommended.

1.5K (Steel) "Well on"


Cell D.B. 228' 568E. F.P.T. 122E. A.P.T. 234E

FK. 7BH. pl cam. Legs area. P 28' Q 75' B 58' F 28'

M  
29.6.18

Certificate of Classification, to be endorsed  
"Repairs not fitted," and the same  
reason to be printed in the Register Book.

The Surveyor should state the size & number of  
rows of pillars fitted in the erection as this information  
has been omitted from the report.



© 2021

Lloyd's Register  
Foundation

W763-0158

BEAMS.