

1

Sent to Chief Surveyors 15.7.14

Received from Chief Surveyors

VESSEL'S NAME Steel 1/2" Sharon

Report Sld. No. 26155

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

Damage

When due

The class of this vessel is subject to the saloon skylight and companion door being permanently repaired at the Owners' convenience.

In reply to enquiry the Sunderland Surveyors now state that the saloon skylight and companion door were repaired when the vessel was under survey at their port last month.

It is submitted the vessel appears worthy to remain as classed without fresh record of survey, without special condition.

as now, without etc.



15.7.14.

© 2020

Lloyd's Register
Foundation

W768-0031