

23 OCT 1940

d by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

L'S NAME "ST CLEMENT" Rpt. Abn No. 20416

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The 1st S.S. No. 3 became due 6.40.

The class is subject to indented shell plates B.4 and 6 (s.s.) and C.3 and D.3 (p.s.) being dealt with at Owners' convenience.

The ABERDEEN Surveyors now report the vessel placed in dry dock, the bottom coated, some shell riveting renewed, and minor repairs carried out.

The stem and some stem plating was found set over but is considered efficient meantime.

The Surveyors recommend the indented plating and stem be repaired at the Owners' convenience.

It is submitted action be deferred.

Insert in S.R.L

Repairs to stem and stem plating.



© 2020

Lloyd's Register
Foundation

21/10/40
W 77-0088