

9 APR 1941

Report to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME "RODNEY STAR" Report Liv No. 115785

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Equipment When due -

Subject to indented shell plating (p & s.a) being dealt with and shell plate A.4 (s.s) being renewed, at the Owners' convenience, to shell plate No. 9 in 5th strake below sheer (s.s.f) E.W. 12.40, being specially examined at the next dry docking, to permanent repairs to pierced or scored shell plating etc. at the earliest opportunity (and to a bower anchor being supplied).

was
7.4.41

Stalkey
S.M.



© 2020

Lloyd's Register
Foundation

W77-0118