

Reinforced Concrete Motor Vessel "VIOLETTE".

This vessel recently sustained severe damage and the class was expunged from the Register Book.

The case was considered by the General Committee at their Meeting on the 17th instant, when it was decided to furnish the Owners with a copy of the Surveyors' report relating to the damage.

Both the Owners and the Underwriters' representative now desire to be informed if the Society is of opinion that the vessel cannot be repaired in such a manner as to entitle her to re-classification.

The Surveyors who carried out the survey have been requested to report upon this point, and it will be seen from their reply, attached hereto, that they are of opinion that a satisfactory repair for the purposes of re-classification cannot be effected.

This opinion is concurred in.

W
C.F.
F.R. 23.2.21



© 2021

Lloyd's Register
Foundation

W781-0084