

W792-0111

F.E.

Inspected by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME ^{QU} *Steel S.S. "SOUTHGAY"*

Rpt. *Dun* No. *8313*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. *51-25* Depth "d" *15-6*
 Framing: Table No. *3* Description *Bulb angle as approved*
 Longitudinal No. *10250*
 Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{10-96}{}$

~~Deck~~ Sheerstrake *as approved*

Hand pumps to the holds have been dispensed with but it is concluded the Owners are agreeable to fit same or their equivalent when required

This vessel appears to have been built in accordance with the rules and the approved plans, and it is submitted she is eligible to be classed

*✱ 100-A-1. (Steel)
1 Dh. (Steel)*

*Cell IB 150' 225", ITF 18' 117", Deck tank 8' 117", FPT 39", APT 40"
FK, ABK, Cem, Rlyths Av CP, F 30', Mchly Off*

Certificate of Classification, to be endorsed "go battens not fitted," and the same to be printed in the Register Book.



© 2021

Lloyd's Register Foundation