

LANK.

THICKNE

In Ship. Pe
ApIns.
2-4-8-2

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME WOOD S. "HYASTAN"

Rpt. Rangoon No. 319

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

First Entry.

Before this case reaches the consideration of the Committee, the Surveyor should be requested to furnish fresh particulars of the following items and particulars given in report do not agree with approved plans.

Siding & Moulding of Floors, footboards and top timbers.

Size of Second Deck beams.

Width & thickness of Upper Deck planking.

Size and number of bilge logs.

Diameter of bolts in Deck shelves.

Number of planks between butts on the same timber.

& Length of Stream chain

The Surveyor should also state if the pumps are fitted as required & if so whether they are satisfactory, if the ceiling is edge bolted, and if the wales are edge bolted or diagonal iron plates fitted as per section 39.

R 27.11.19.

M. A. S.
27-11-19

© 2020

Lloyd's Register
Foundation

W 860-0083

Surveyor's Signature

Surveyor to Lloyd's Register of Shipping.