

Have Report n^o 2590^a

It is submitted that before this case receives the consideration of the Committee, that the plan of the main boilers should be returned to the Have surveyors, & they should be requested to state whether these boilers have been built in accordance with the approved plan, in view of their statements in their Report that the thickness of front plates at bottom are $1\frac{9}{32} + \frac{1}{16}$, thickness of lower back plate $1\frac{3}{16}$ " & diam. of plain tubes $2\frac{3}{4}$ ", & greatest pitch of stays at lower back plate 5'-9", which sizes do not correspond with the approved plan.

Dr: - 13/1/08

J. F. L.
13.1.08



© 2021

Lloyd's Register
Foundation

W932-0122