

the following repairs were completed to my satisfaction.  
Casings completed & riveted up

by Chief Ship Surveyor

Received from Chief Ship Surveyor

'S NAME Steel S.S. "JACOBUS" Rpt. Hul. No. 31804

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey First Entry

Before this case receives the consideration of the Committee the Surveyors should be asked to state whether the Watertight Door & Pumps have been tested & found efficient working order, also whether the tank top plating has been increased in thickness as required in lieu of ceiling

*see letter to [unclear] 1/10*

8.5.20

*M. A. B.*  
8-5-20



© 2020

Lloyd's Register  
Foundation

Age or Repair Fee (if any) £

19  
Received by me,

*James Green*