

And what parts of the Boilers could not be thus thoroughly examined?

... means, in the absence of internal examination, were adopted by the

... of each Boiler 2.

4m, 11.98.

Received by Chief Engineer Surveyor

VESSEL'S NAME

"JEANNE M"

Received from Chief Engineer Surveyor

Rpt.

Cff.

No. 53689

2 E

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

Nature of Survey COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No.

MAIN

now

This Survey, due 7.40 now partly held
completed, and the following repairs carried out (due to wear and tear):-

2 tubes renewed.

It is submitted the vessel is eligible to remain as classed, with notation of DBS 5.40, MBS 11.40

as recommended.

S.S. No.2 due 9.40.



© 2020
Lloyd's Register
Foundation

exten
ngs.

ed

pipe
3606