

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as  
painted on Ship and now verified

Chief Surveyors

Received from Chief Surveyors

27 JAN 1940

EL'S NAME

HAXBY

Report

LIV.

No. 113691

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

e of Survey

GROUNDING

When due

Subject to indented bottom plating and buckled  
internal structure in NOS 5 & 6 D.B. tanks being  
repaired at the first convenient opportunity.

was  
27-1-40



© 2020

Lloyd's Register  
Foundation

Inner Bottom Plating where exposed good

Have the Tanks been examined internally no str.

Have the Tanks been tested? no str.

and found efficient? yes

Air and Sounding Pipes good

Doubling Plates under Sounding Pipes indented

Stringers, Clamps & Shelves

Salting

(State if examined.)

Hawsers & Warps

Standing and Running R

Sails