

London, E.C.3.

71, Fenchurch Street,

Dec '41 (WE)

DIRECTORS:

F.C.A.

TELEGRAMS: LLOYD'S REGISTER, LONDON

15 DEC 1941

9 - DEC 1947

ed by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

EL'S NAME "LANGLEEGRAG"

REPORT

Hul.

No.

54515

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to permanent repairs to indented shell plate etc. (p & s) at the first opportunity.

The HULL Surveyors report the vessel placed in dry dock, bottom coated, rudder gudgeons rebushed and minor repairs effected.

On account of heavy weather damage, temporary repairs effected to shell plates G.2 and F.2<sup>(p & s)</sup> (fractured) at heels of frames and ends of stringer lugs. The Surveyors recommend permanent repairs at the first convenient opportunity.

IT IS SUBMITTED the vessel is eligible to remain as classed, with record of docking survey 11.47, subject as above and to permanent repairs to No.2 plates in F & G strakes (p & s) at the first convenient opportunity.

11.47 Hul. *Subject.*



© 2020

Lloyd's Register  
Foundation

Sails