

age cases where the Surveyor has not made a special damage report he is required to state whether he offered his  
 vices for this purpose, and why they were declined ✓

14.47  
 SS. 841 N° 3-1.

"LANGLEECRAG"

Hul. 54515

The Hull Surveyors report that some pumps have been examined and repairs effected at this time and have been examined under steam on completion and considered efficient until the next LMC Survey.

The Machinery Survey on this vessel will become due in 1.48, but as this survey might not necessarily be held at the due date IT IS SUBMITTED that before this case receives consideration the Surveyor should state whether any special condition regarding a further examination of these pumps should be placed on the vessel's class. Their remarks are awaited.

X

See Hull reply 10.12.47

YRm

8. 12. 47.



© 2020

Lloyd's Register  
 W9938-0136

dep feed pumps:- suction & dell valves repaired & piston & true belt  
 rod of after pump machined & bushes renewed.  
 Up-circ pumps:- crankshaft skinned up at ends & new flywheel fitted;