

Tanker "MARKAY"

This tanker suffered considerable damage to the bottom forward of amidships and extensive temporary repairs are to be carried out to permit the vessel proceeding to America for permanent repairs. Certain recommendations made by Mr. Stocks were the subject of special discussion in this Office (see attached copy of endorsement).

Mr. Finnigan, the Owners' Representative, called at this Office yesterday and expressed his thanks for the assistance which had been afforded him in this matter and his appreciation of the work done by Mr. Stocks and Mr. Reid, not only in the way of helpful suggestions but by preparing special sketches. He stated that he would not fail to report to his Owners how much they were indebted to Lloyd's Register in connection with this case.

[Handwritten signature]

[Handwritten signature]
1.3.44.



© 2020

Lloyd's Register
Foundation

W996-0111

affected on arrival at a U.S.A. port, being fit to proceed in ballast (at draughts approximately 8ft. forward and 22ft. aft). The vessel's...
structure and fittings being

in bu...
19,42...
150° F...
A.B.A...
riters'
ue to:-
er, 1943...
s found:
nd of No...
of No. 4...
ft end...
lge in No...
Year...
Go...
ained From de...
removed...
f +
3B. 1S...
ranged) Not r...
mean diamr...
size...
Not exd...
Sufficie...
Rigging... Go...
it...
work done upon...
no record of...
fresh record of sur...
ature and fittings being