

examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

4 E

Engineer Surveyor

Received from Chief Engineer Surveyor

NAME

"BRITISH MERCHANT"

REPORT

Npt.

No. 25 546

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

is endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.)


~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

Special Survey due 11.51 has been partly held now.

Various repairs have been recommended, but not carried

at.

IT IS SUBMITTED action be deferred.



© 2020

Lloyd's Register
Foundation

17. 10. 49.

W999-0129

page 2.