

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19 4/2 1925 Port of Hull
 When handed in at Local Office 4/2 1925
 Date, First Survey 7. 1-25 Last Survey 21-8-1925
 (No. of Visits 2)

Sailing Ship Sup. *Subh*
 No. in Reg. Book. 55858 on the Wood, Iron or Steel Sc. "LIZZIE & ANNIE"
 Survey held at Hull
 TONNAGE:- Built at North Shields. By whom J. Softley & Sons. When 1877 6.
 GROSS 119 Owners G. F. Birch & Sons (1919) Ltd. Owners' Address
 UNDER DE. 96 Managers
 NET 65 Port belonging to Hull

Surveyed Afloat or in Dry Dock? dry dock. Name of Dock Drypool. Destined Voyage
 WB=CellDBorDBa feet; uE&B feet; f feet } Particulars of Classification (which must be inserted
 total capacity tons. FPT tons; APT tons; MT feet tons. } precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 88486 Port LON

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified 11 1/2 ins.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition.

The vessel placed in dry dock. Bottom, keel & rudder cleaned, examined, found in good condition & recoated. Ventilators & their coamings examined & found in good condition. Engine seating examined. Blank flanges removed from ends of stern tube, & machinery refitted. (See Hull Report No. 35596.) The freeboard assigned to this vessel before the removal of the machinery has now been re-marked & verified.

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Faired or Repaired ...								
Faired or Repaired in place ...								

PRESENT CONDITION OF THE

Decks <i>Good</i>	State if Tanks have been examined inside	Dblg. Plates under Sounding Pipes	Copper, or I.M. of Wood Vessels (State if on Fell)
Caulking of Decks	State if Tanks now tested	Engine Room Skylights <i>good</i>	When put on, Month Year
Coamings	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	Boats <i>good</i>
Beams & Fastenings	Ceiling	Scuppers <i>good</i>	Masts, Yards, &c.
Outside Plating	Cement or Asphalt (State which.)	Cargo Hatchways	Condition, how ascertained <i>from deck</i>
Breasthooks	Rudder <i>good</i>	Hatches	(State if wedges removed) <i>no</i>
Transoms	Steering gear and its connections	Planking of Wood Vessels	Sails
Frames	Windlass	Caulking ditto	Equipment letter <i>a</i>
Reverse Frames	Have Pumps now been examined and found efficient?	Treemalls ditto	Anchors, No. of <i>20 15</i>
Longitudinals	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	Cables (State if now ranged) <i>no</i>
Transverses	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	" length (on board) size
Floors	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	" Rule length size
Keelsons		Ditto ditto at other places ditto	Hawser & Warps <i>Sufficient</i>
Stringers		Stringers, Clamps & Shells ditto	Standing & Running Rigging <i>good</i>
Inner Bottom Plating		Setting (State if examined) ditto	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND15, &c."

This vessel as far as now seen is in good & efficient condition, & eligible in my opinion to be retained to her previous class - *1-90 A1* - in the steamer & motor ship register book, with fresh record of survey 1.25.

Survey Fee (per Section 29)	£	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	19
Travelling Expenses (if chargeable)	£	Received by me,
Second Surveyor's Fee (if any)	£	19

P. Fitzgerald.

Surveyor to Lloyd's Register of Shipping.

Committee's Minute
 Write *Box*
 Character Assigned

FRI. 6 FEB 1925

90 A1

Large battens not fitted
 d.m.c. 1.25

CERTIFICATE WRITTEN



© 2018

Lloyd's Register Foundation