

"Bakuin"

Apr 8036

24. 5. 90

In consequence of there being a quantity of petroleum mixed with the water in the tanks, ~~and~~ the dock authorities would not allow same to be discharged & consequently surveyor was unable to examine the asphalt. This however will be done when vessel is submitted to S.S. No 1.



© 2018

Lloyd's Register  
Foundation