

Date of writing Report 24th April 1912 When handed in at Local Office 24th April 1912 Port of Antwerp.

L 2 on the ~~Wood, Iron or~~ Steel S. S. "Baku Standard" Master A. Torrance.

3708.

ORDER NO. 2245

Owners' Address

Surveyed April 10 in 1882. Depth 10 fathoms. Distance 10 miles. Direction of voyage N. by E.

N.B.—All alterations in the existing records should be underlined.

Last Report	No 59875	Port	Price	+100 A.1. Spar dk. 2.11.	+4. M. C. 1.11.
-------------	----------	------	-------	--------------------------	-----------------

(Periodical Surveys, when held, must be reported in detail and serialism in the terms of the Rules. State clearly the cause of repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs

replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition.

...the little ...

A few defective shell rivets in way of the Engine Space cut out and renewed.

The steam did not injure and no connections weakened, during tests renewed,

mindless overhauls and a fraction of minor deck repairs carried out

SUMMARY OF DAMAGE REPAIRS :--	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Repaired :								
Estimated :								
Total :								
Remarks:								

[illegible]

Decks Fore. Inner Bottom Plating ✓ Engine Room Skylights Fore. (State if on Fore.) When put on, Month Jan. Year 1900

Waterways.....	State II TANKS NOW TESTED.....	Scupperns.....	Masts, Yards, &c.....
Bulkheads.....			

Outside Plating	Cement or Asphalt (State which.)	Planking of Wood Vessels	(State if wedges removed)

Rivets	Steering gear and its connections	Treenails	ditto	Equipment letter
	Windlass	Breasthook & Stowman		

Frames..... *Look* ✓
Timbers of Frames at openings ditto.....
Cables (State & how ranges).....
length ✓ size ✓

Floors	Where exposed	Have Watertight Doors now been examined and found	Stringers, Clamps & Shells	ditto	Hawser & Warps	Insufficient
			Saltin	ditto		

General Observations. Opinion as to Class. Recommendation &c. —

survey, 1,10," or "to remain as classed and to have record of survey, 1,10, and the notations of *as No. 1-10 and ptND10, &c.*"

... in regard to my opinion a summary is needed and to have

Survey Fee (per Section 29) 2.00

Special Damage or Repair Fee (if any) (per Sec. 22) £ 10.00

Received by me.

Second Surveyor's Fee (if any) : : £

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute FRI. MAY 10. 1912

Spas dlu