

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report

When handed in at Local Office

5 NOV 1918

Port of

No. in
Reg. Book

Survey held at

South Shields

Date, First Survey

25 Oct

Last Survey

29 Oct 1918

1941 on the Wood, Iron or Steel SS "STETTIN"

Master

TONNAGE:-

GROSS 876

UNDER DECK 857

NET 529

Built at

Glasgow

By whom

Barclay Curle & Co

When

1864

MONTH

Owners

J. Currie & Co

Port belonging to

Leith

Owners' Address

(If not already recorded in Appendix to Register Book)

Surveyed Afloat or in Dry Dock?

Dry

Name of Dock

Smiths High.

Destined Voyage

WB=CellDBorDBa

feet; u&B

feet; f

feet; f

total capacity

tons. FPT

tons; APT

tons; MT

feet

tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 70201 Port

Hull

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER, for Special Survey, Date of last Survey and of Particular Surveys.	Year of last Survey	Year of last Particular Survey
+ A 1	9-17	SS Lth 4" HCS 4-15
+ N/B 12-89		
+ LMC 6-15		
BS 9-17		

Society's Freeboard (if assigned) as painted on Ship and now verified

NTS 9-17 NAB 89
NTS 7-15 Tpd 19

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined?

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Bottoming

Vessel placed in dry dock,

bottom rudder examined, cleaned, riveted, rudder lifted and refitted.

A few shell rivets renewed, a few wood hatches renewed.

On the fore foot the U shoe plates fitted on some previous occasion were found much worn, and instructions were given to have three lengths renewed. Owing to scarcity of labour this could not be done & it is recommended that these be dealt with next dry docking. In my opinion this proposal merits approval.

SUMMARY OF DAMAGE REPAIRS:-

Renewed

Removed and Faired or Repaired

Faired or Repaired in place

Plates

Frames

R. Frames

Floors

Beams

Str. Plates

Dk. Plates

Other Items:-

PRESENT CONDITION OF THE

Decks

Caulking of Decks

Waterways

Coamings

Beams & Fastenings

Outside Plating

Caulking of ditto

Rivets

Breasthooks & Crutches

Transoms

Frames

Reverse Frames

Floors

Keelsons

Stringers

Inner Bottom Plating

State if Tanks have been examined inside

State if Tanks now tested

Bulkheads

Ceiling

Cement or Asphalt

Killer

Steering gear and its connections

Windlass

Have Pumps now been examined and found efficient?

Have Slide Valves now been examined and found efficient?

Have Watertight Doors now been examined and found efficient?

Dblg. Plates under Sounding Pipes

Engine Room Skylights

Coal Bunkers Open'gs, Lids, &c.

Scuppers

Cargo Hatchways

Hatches

Planking of Wood Vessels

Caulking

Treenails

Breasthooks & Beams

Transoms, Pointers, & Crutches ditto

Timbers of Frame at openings ditto

Ditto ditto at other places ditto

Stringers, Champs & Shells ditto

Siding

(State if examined.)

Copper, or Y.M. of Wood Vessels

(State if on hull.)

When put on, Month

Year

Boats

Masts, Yards, &c.

Conditions, how ascertained

(State if wedges removed)

Sails

Equipment letter

Anchors, No. of

Cables (State if now ranged)

length

(on board)

Rope length

Kawser & Wages

Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and PSD15, &c."

This vessel is now in my opinion eligible to remain as classed with record 10-18 Shl subject to fore foot shoe plates being dealt with next dry docking.

Survey Fee (per Section 20)

Special Damage or Repair Fee (if any)

Travelling Expenses (if chargeable)

Second Surveyor's Fee (if any)

Fees applied for

Received by me

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

Character Assigned

FRI. 22 NOV. 1918



© 2018
Lloyd's Register
Foundation