

Submitted the Surveyor be requested to report the height  
 of sill of the lowest additional sidescuttle ~~above~~ above top  
 of keel, since foreward may be affected if the sidescuttles  
 are not of approved underwater pattern.  
 (Return accompanying copy of C.11 (anti) for placing  
 on board ship).

1/12 [26007] 1500

