

TRANSPORT FERRIES.

Additional Stiffening.

Service experience has shown that additional stiffening is required at the stern of these ships and a plan has been prepared by the Admiralty, after consultation with this Society, showing the modifications required.

It is submitted that a copy of this plan be sent to the Montreal Surveyors for their information, and that Captain Miskin should be informed that some additional stiffening will be required in the case of the Transport Ferry 3519. This stiffening should be carried out at the first convenient opportunity.

7.8.46.



© 2018

Lloyd's Register
Foundation