

1 OCT 1947

Surveyor.....

Received from Chief Ship Surveyor.....

EMPIRE CEDRIC

REPORT

Lon.

No.

115422

Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points of endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to permanent repairs to indented bow plating at the first convenient opportunity and to stiffening of stern moved being effected at the first opportunity.

The LONDON Surveyors report (8.47) ship afloat and new bow doors examined, found constructed in accordance with approved plans, in place and found satisfactory.

On account of tank top leakage, cause not stated, No. 19 double examined, temporary repairs effected to riveting of slightly distorted transverse beams, and permanent repairs recommended by the end of November 1947, this tank to be kept either full or empty whilst at sea permanently dealt with.

It is submitted this ship is worthy to remain as classed, subject as to permanent repairs to slightly distorted transverse beams and to black riveting in way of No. 19 D.B. tank before the end of November 1947, this tank to be kept either full or empty whilst at sea until permanently repaired.

subject.

29
2
44



© 2018

Lloyd's Register
Foundation