

1 E

by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

S NAME "DALKEY COAST" REPORT Ham. 2496.  
 Ams. N. 18636.  
 Augs. 187.

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine Oil Engine 4 SCSA.

8 cyl. 12" - 18. 1/8"

New MN 160.

~~If Boilers fitted with forced draught~~

Tail Shaft. If fitted with a continuous liner Yes.

If fitted with an outside gland of approved type No

The torsional vibration characteristics of the main propelling machinery were approved in the Secretary's letter of 14.9.53 for a service speed of 350 rpm, provided a notice board be fitted at the control station stating that the engine is not to be operated continuously between 215 and 245 rpm and the tachometer be marked accordingly. The machinery certificate should be endorsed accordingly and a suitable entry made in the S.R.L.

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed LMC 6.53.

*End for A.D.H.*

17.9.53.



© 2020

Lloyd's Register  
Foundation