

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do.

"

Donkey "

"

"

If this was not done, state for what reasons?

hot due for survey

S.S. "CHANNEL QUEEN"

Nwc. 74916
Dnk. 2182
Nwc. 74885
Sou. 10638
Mdb. 10939

The machinery of this vessel was completed and tried under steam in October last and recommended for the record of LMC 10.21.

During the maiden voyage from the Tyne to Calais a large crack developed at the lower part of the condenser. This was temporarily repaired to enable the vessel to return to Newcastle. The Newcastle Surveyors have now recommended further temporary repairs until a new condenser is ready for fitting.

The screw shaft has been examined and the propeller renewed.

It is submitted that this vessel is eligible for the record LMC 10.21. C.L. subject to a new condenser being fitted.

Note S. 11.21.

9.11.21.

Ans.



© 2020

Lloyd's Register Foundation

002165-002173-0131

666

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

If Stockless, state Mechanical Tests.

under steam P
under steam ?
oller ?
oller ?
oller ?
oller ?
or is it with
it without li
a w
tinnou
ne
reine
actur
of c
ight
e w
form
consequent
S.S. 9.11, B.&
ter of
the ta