


near to be very strong. The bolts were all very well
Next the place where the joint of the air pump suction
1st condenser, vertical side, a crack

S.S. Channel Queen

Box 2/P2.

Submitted this report be forwarded to the
five surveyors for their information & guidance

A.
22/10/21



© 2020

Lloyd's Register
Foundation

002165-002173-0141

on Proc JV 749/16

002165-00