

1

ATLANTIC UNITY

Orinjal Dragon ex Bellemina

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME STEEL S.S. "BELLEMINA"

Report N.Yk.

No. 17516

For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

The Downton Pump has been dispensed with for the present.  
60 fathoms Chain Cable of Cast Steel.

100 A.1. (steel) "Shelter Dk with Freeboard"

1 Dk (steel) and Shelter Dk (steel) and Webframes. Longitudinal Framing"

Cell DB 331 1512t. FPT 187t. APT 175t.

FK. 7 BH to Shelter Dk. pt. cems. A+C.P. P45', B110', F38' on Shelter Dk.


50  
4/12/19  
also re notation  
for "re"  
to be

M. A.E.S.  
12-11-19

It is concluded the Watertight Doors are in efficient working order & that the tests for Chain Cable, certificate No 181, are as required for cast steel cables, but the Surveyors should be requested to state if this is so.

The Surveyors should also state if Oil Fuel is being carried as cargo in Double Bottom & Peak tanks.

002215-002221-0089



© 2020

Lloyd's Register Foundation