

00249-00259-0074

Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

NAME Stl S KALAVATI

Report

No.

48639

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Survey 1<sup>st</sup> Entry When due Old Rule

❖ 100 A.I. (Steel). Shelter D<sup>k</sup> with Freeboard

1 D<sup>k</sup>. Shelter D<sup>k</sup> (Stl - leaks).

Cell D.B. E 25' 53t, F.P.T 55t, A.P.T. 62t.

F.K 5 B.H (Coll B.H to Shelter D<sup>k</sup>, H.B.H to upper D<sup>k</sup>) pt cem pt asp. Lloyd's ACP.  
F 34'.

is concluded the Collision bulkhead extends to the shelter  
dk and the remaining bulkheads to the upper D<sup>k</sup>  
the. Surveyor should be requested to state if  
is is so

© 2020  
29.11.28  
Lloyd's Register  
Foundation