

ed by Chief Ship Surveyor

Received from Chief Ship Surveyor 12 DEC 1921

SEL'S NAME *Steel S. S. 'MORETON BAY'*

Rpt. *Liv*
Run

No. *82974*
85023

he remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

re of Survey

DAMAGE.

Damage through *Course not Stated* and *Slipping a lower Anchor and 15 fathoms of Cable*
now repaired as follows:-

	Plates	Frames	R.Frames	Floors	Beams	Str.	Plates	Dk.	Plates
Renewed									
Removed and faired or repaired.....									
Faired or repaired in place.....	<i>2</i>	<i>2</i>		<i>1</i>					

Other items:- *Vessel placed in dry dock bottom cleaned examined and Coated*
and minor repairs effected

A testis Cable Shackle placed on board

It is submitted the vessel is worthy to remain as classed with

record of Survey *Bkn 11.21* ~~as recommended~~

100-A-1. Shelter Deck with subboard
11.21 Bkn.

Fitted for 600 fuel etc

© 2020
Lloyd's Register
Foundation
002289-002297-0181