

The hinged steel door on port side of the  
after bulkhead of the forward bridge  
has now been closed by a riveted steel  
plate. See Journ. C-1(a). 7/7/36

Rev 27/7/36

RETAIN



© 2020

Lloyd's Register  
Foundation

002385-002400-0218