

Speadrott.

It is concluded that a spare
lubricating oil pump with connections
is fitted but this should be confirmed.

L. 379/19

G.A. 24/8/29 J.H.

002385-002400-0241