

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *S.S. "Carlbeath"* Rpt. *Lth.* No. *16628*  
*16623*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

Transverse No. *6962* Depth "d" ✓  
Framing: Table No. ✓ Description *Bull angle as approved.*  
Longitudinal No. *17854*

Proportions Length = *10.78*  
Depth =

*Deck Sheerstrake and other scantlings as approved for a vessel built on the "Arch Deck" system. Revised Rules.*

*"This vessel, received damage through striking quay wall, temporary repairs have been effected & the Surveyor recommends permanent repairs be effected at the first convenient opportunity."*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed **✦ 100 A1 (Steel)** with freeboard," as recommended *subject as recommended*. The Summer freeboard of *6' 11 1/2"* from centre of disc to top of statutory deck line at *upper* deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

**✦ 100A1 (Steel) "with freeboard" (Subject ✦)**  
*1 DK (Stl.) "Arch deck"*

*cell D.B. 231' 5926. D.T. in E.R. 13' 1396. F.P.T. 906. A.P.T. 1016.*  
*F.K. 4 B.H. ft. cum. Lloyds A.I.C.P. P. 19' F. 19'*

The Certificate of Classification, to be endorsed

"Cargo battens not fitted," and the same

notation to be printed in the Register Book

*It is concluded the tunnel has been tested but the Surveyor should state if this is so.*

002410-002417-0176

