

1E

ed by Chief Engineer Surveyor

Received from Chief Engineer Surveyor *hwc* 94862

SEL'S NAME

LLANDAFF

Rpt.

Sld

No.

32092

Lon

103861

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92)

Type of Engine C. 4cy. (2) 10 1/4 & (2) 20" — 13"
S.R. geared; & L.P. Turbine O.R. geared to
Screw shaft

If Boilers fitted with forced draught

main boilers — yes

Aux " — no

Tail Shaft. If fitted with a continuous liner

yes


If fitted with an outside gland of

approved type

no

This vessel's machinery appears to have been built in accordance
with the Rules and the approved plans, and it is submitted she is
eligible to be classed + *Lime. S. 37*

2. S.B. (F.O. Spt.) & 1 aux. S.B.




J. Kim

24.5.37



002427-002434-0062



© 2020

Lloyd's Register
Foundation