

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined -

Society's Freeboard (if assigned)
painted on Ship and now v

Was a damage report made by anyone else? if so, by whom? -

REPAIRS, OR EXAMINATION AS PER RULE, FOR Special Survey and Oil Fuel Conversion

New done for Special

COPY

EL'S NAME "ARETI" ex Maria Cristina Report LISBON No. 5771

KNESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in **Decimals** of an inch.

TRAKE.	AMIDSHIP.				FORWARD.				AFT.				REMARKS.
	Original Thickness.	Thickness by drilling		Diminution if any.	Original Thickness.	Thickness by drilling		Diminution if any.	Original Thickness.	Thickness by drilling		Diminution if any.	
		Port.	Std.			Port.	Std.			Port.	Std.		
SHEER STRAKE.													Orig. Drllgs.
elow.	L.	62.62.59			-	-	-		-	-	-		Poop (PS) .34 ✓ .230
STRAKE	K.	56.55.47			-	-	-		-	-	-		" (SS) .34 ✓ .35
ke below	J.	90.74.70			42.55.51				42.59.51				✓
"	H.	56.31047			42.31047				42.23047				✓ Fool. (PS) .38 ✓ .230
"	G.	56.43.51			42.39.310				42.230230				✓ (SS) .38 ✓ .270
"	F.	56.47.47			42.47.35				42.43.270				✓
Bilge	E.	56.51.51			42.43.39				42.230270				✓
Bilge	D.	56.47.51			44.47.270				44.230270				✓
"	C.	56.51.55			44.47.270				44.35.35				
"	B.	56.55.51			44.310270				44.47.35				
"	A.	56.51.55			44.59.55				44.39.35				
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"													
"	</												

Plates marked thus ϕ renewed in original thickness
adjacent plates drilled and renewed where necessary.

Drillings at ends to be made in the vicinity of the peak bulkheads.

002465 - 002470 - 0075

Keelsons " "
Stringers " "
Inner Bottom Plating " "
Have the Tanks been examined internally? **yes**

Have watertight Doors been examined and found efficient? **yes, good**
Have Ventilators and their Coamings been examined and found efficient? **yes**

Transoms, Pointers & Clutches
Timbers of Frame at openings
" " at other places
Stringers, Clamps & Shelves

Copper, or Y.M.
(State if on)
When fitted, by

Boats

Masts, Yards,

Condition, how
(State if we)

Equipment letter

Anchors, No. o

Cables (State if

" length

" Hole length

Chain Locker

Hawsers & W