

002485-002489-0054

Empire Fibroch


Grk 22042 Ruc

to Lloyd's Register 10/4/42

The Surveyors should state what alternatives means there are for circulating the sea condensers, whether the spare gear was checked on board & whether the Exhaust Steam has connections to main & aux. Condensers. They should make this clear in future reports.

clear on his report.

27/10/42



© 2020

CERTIFICATE WRITTEN

Lloyd's Register
Foundation

by J. Sepey
28/10/42